



HP Indigo Technical Marketing

April 2006

Discontinuance Policy for Digital Front End Equipment

HP Indigo provides technical support, maintenance services and spare parts for Digital Front End equipment, for at least five years after production is discontinued.

After the five year support period, HP Indigo will make special efforts to continue to provide the above services to our customers subject to the availability of spare parts and other technical support services.

As of April 2006 HP Indigo has discontinued the products listed in the table below.

The discontinuance notices are published on the HP Indigo internet web site:

<http://www.hp.com/go/indigo>

Click **My HP Indigo** and sign in
Press (under *Technical Support*)
Press Documentation
Discontinued products

Yours sincerely

Aaron Lubelski
 Technical Marketing – Support manager

HP Indigo discontinued DFE products as of April 2006

Part Number	Product Description	Operating System	Server Type	Production discontinuation	End of support	Replaced by
MPS-2801-10	HP Prod. Flow - Server (English only)	Windows 2000 Server	ML530G2 Q1316A	October 2004	December 2009	Q4879A#ABA
MPS-2801-20	HP Prod. Flow - Server (EFIQS)	Windows 2000 Server	ML530G2 Q1316A	October 2004	December 2009	Q4879A#416
MPS-2802-10	HP Prod. Flow - Server&RIP (English only)	Windows 2000 Server	ML530G2 Q1326A	October 2004	December 2009	Q4880A#ABA
MPS-2802-20	HP Prod. Flow - Server& RIP (EFIQS)	Windows 2000 Server	ML530G2 Q1326A	December 2005	December 2010	Q4880A#416
MPS-2803-10	HP Prod. Flow - Server & Dual RIP (English)	Windows 2000 Server	ML530G2 Q1327A	November 2004	December 2009	Q5938#ABA
MPS-2803-20	HP Prod. Flow - Server & Dual RIP (EFIQS)	Windows 2000 Server	ML530G2 Q1327A	December 2005	December 2010	Q5938#416
MPS-2804-10	HP Prod. Flow - Server & Quad RIP (English)	Windows 2000 Server	ML530G2 Q1328A	December 2004	December 2009	Q5939#ABA
MPS-2804-20	HP Prod. Flow - Server & Quad RIP (EFIQS)	Windows 2000 Server	ML530G2 Q1328A	March 2006	December 2010	Q5939#416
Q5936A#416	HP Production Flow - Server (EFIQS)	Windows 2000 Server	ML370G3	December 2005	December 2010	Q4879A#416
Q5936A#ABA	HP Production Flow - Server (English)	Windows 2000 Server	ML370G3	December 2005	December 2010	Q4879A#ABA
Q5937#416	HP Production Flow - Server & RIP (EFIQS)	Windows 2000 Server	ML370G3	December 2005	December 2010	Q4880#416
Q5937A#ABA	HP Production Flow - Server & RIP (English)	Windows 2000 Server	ML370G3	December 2005	December 2010	Q4880#ABA

Copyright notice and disclaimer

© Copyright Hewlett-Packard Development Company L.P.

Reproduction, adaptation, or translation without prior permission is prohibited, except as allowed under the copyright laws.

The information contained herein is subject to change without notice.

The only warranties for HP products and services are set forth in the express warranty statements accompanying such products and services. Nothing herein should be construed as an additional warranty. HP shall not be liable for technical or editorial errors or omissions contained herein.